

**Notice of Network Change – Spartanburg, S. C.
Digital Cross-connect System (DCS) Conversion**

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to occur: First Quarter 2004

Location of Changes: Spartanburg, South Carolina

Description of Change Planned: Spartanburg, S.C. Digital Cross-connect System Conversion: The current Lucent DACS IV DCS (SPBGSCMAK11) will be removed. Existing service will be re-terminated to a Tellabs TITAN 5500 DCS. The new Common Language Location Identifier (CLLI) will be SPBGSCMAK15.

Description of Reasonably Foreseeable Impact of the Planned Change: The new DCS will require the customer Carrier Facility Assignment (CFA) to change. To help ensure a smooth transition, BellSouth will provide Facility Trunk Group Service Request Forms (TGSR). Interconnecting carriers planning to submit Access Service Requests (ASR) should indicate their intent on the TGSRs that are returned to BellSouth.

Contact: Technical questions relating to this change should be directed to: C. J. Hilliard, Manager- Network
4th Floor, 1600 Williams Street
Columbia, South Carolina 29201
803-401-2968

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191